60 Cwmphil Road, Lower Cwmtwrch

Property Information Questionnaire

60 Cwmphil Road Lower Cwmtwrch, Swansea, SA9 2QB Kotini has gathered this property information, and the sellers have confirmed it to be accurate as of:

22/12/2025 19:22

Introduction

Estate agents are required to provide consumers with 'material information' in property listings to ensure they can make an informed decision when buying a property. Material information is information that the average person needs to make an informed transactional decision#basically, whether a buyer decides to enquire further, view, or buy a property.

The estate agent you're buying from is dedicated to helping people find the right property for them and, as such, has put together this comprehensive report of the property you're looking to buy, helping you to make an informed purchasing decision.

If you have any questions about the information contained in this report, please contact your estate agent.



Contents

- %	12

Additional information

Alterations & changes

Boundaries

Completion & moving

Connectivity

Council Tax

Displutes & complaints

Electricity

Electrical works

Energy efficiency

Environmental issues

Guarantees, warranties, and indemnity insurances

Heating

Insurance

Listing & conservation

Notices

Ownership

Parking

Rights and informal arrangements

Services crossing the property

Specialist issues

Type of construction

Water & drainage



Additional information

Other material issues

No

Other charges not mentioned elsewhere

No

Non-compliant with restrictions on use and alterations

No



Alterations & changes

↓ Structural alterations

Structural alterations made to the property

No

↓ Change of use

Property subject to a change of use

No

→ Windows, roof windows, roof lights or glazed doors installations

Windows, roof windows, roof lights or glazed doors installed since 1st April 2002

No

↓ Conservatories

Conservatory added to the property

No

Unfinished works at the property

No

Unresolved planning issues

No

Planning permission breaches

No



Boundaries

↓ Boundary ownership	
Front boundary Seller	
Left boundary Neighbour	
Rear boundary Seller	
Right boundary Seller	
Boundaries are uniform Yes	
Boundaries have been moved No	
Property boundaries differ from the title plan	
Proposal to alter the boundaries No	
Adjacent land included in the sale	

Details of the parts of the property outside the sellers legal ownership	
	Part of the property are outside the legal ownership of the seller Yes
	NO .
	No

Back lane access to rear, this has surpassed the 20 year mark and we have a legal right away.

Flying freehold at the property

Part of the property on separate deed

No



Completion & moving

Any dates the seller can't move on	
No	
Property in a chain	
No	
Sala price sufficient to settle the mortage	
Sale price sufficient to settle the mortgage Yes	
Seller will leave all keys	
true	
Seller will remove any rubbish	
true	
Seller will replace any light fittings	
true	
Seller will take reasonable care	
true	
n de	
End of section	
2.12 0.1000.001	



Connectivity

Telephone line connected to the property

Yes

Telephone supplier

Sky

↓ Cable & TV

Cable or satellite TV connected to the property

Yes

Cable or satellite TV supplier

Sky

Broadband connection at the property

FTTP (Fibre to the Premises)

Mobile signal issues at the property

No



Council Tax

Local Authority

Powys

Council Tax band

D

Annual Council Tax

2234.44

Alterations affecting Council Tax band

No



Past disputes and complaints

No

Potential disputes and complaints

No



Electricity

Property connected to mains electricity

Yes

Mains electricity supplier

Utility warehouse

Electricity meter location

Front porch area

↓ Solar or photovoltaic panels

Solar or photovoltaic panels installed at the property

No

↓ Other electricity sources

Other sources of electricity connected to the property

No



Electrical works

Electrics tested by a qualified electrician

No

Any electrical works at the property since 2005

No



End of section

Energy efficiency

Date of inspection 2010-04-15	
Certificate date (valid for 10yrs)	
2010-04-15	
Certificate number	
8070-6824-7230-8495-9992	
Current Energy Performance rating	
E	
Current energy efficiency	
42	
Potential Energy Performance rating	
D S	
Potential energy efficiency	
61	
Constant de al la constant la	
Green deal loan in place No	



Environmental issues



Property flooded before

No

Property at risk of flooding

No



Radon remedial measures on construction

Not known

Radon test carried out

No

↓ Coal mining

Coal mining risk

No

◆ Other mining

Other mining risk

No

↓ Coastal erosion

Coastal erosion risk

No

↓ Other

Other environmental risks

No



Guarantees, warranties, and indemnity insurances

Guarantees or warranties available for the property No
Guarantes or warranties for central heating and/or plumbing No
Guarantes or warranties for damp proofing treatment No
Guarantes or warranties for double glazing No
Guarantes or warranties for electrical repair or installation No
Guarantes or warranties for roofing work No
Guarantes or warranties for solar panels No
Guarantes or warranties for subsidence work No

Guarantes or warranties for timber rot infestation treatment No
New home warranty No
Any other guarantees or warranties No
Outstanding claims or applications against the guarantees or warranties No
Title defect insurance in place No
End of section



Heating

Type of heating system
Central heating
Central heating fuel
Oil
Mains gas, Oil or LPG supplier
Star multi fuels or any other as not contracted
Was a gas boiler installed after 1st April 2005, or a solid fuel or oil boiler installed after 1st October 2010?
Yes
Date of installation

22/07/2016

Date of the last service or maintenance

01/10/2025

Is the heating system in good working order

Yes

Other heating features at the property

Double glazing, Wood burner



End of section

Insurance

Property insured Yes
↓ Insurance concerns
Abnormal rise in insurance premiums No
Insurance subject to high excesses No
Insurance subject to unusual conditions No
Insurance previously refused No
Past insurance claims No



Listing & conservation

↓ Listing status

Listed building in England or Wales

No

↓ Conservation

Located in a designated conservation area

No

↓ Tree Preservation

Tree preservation order in place

No



Notices

Infrastructure project notice(s) No		
Neighbour development notice(s) No		
Listed building application notice(s) No		
Party wall act notice(s) No		
Planning application notice(s) No		
Required maintenance notice(s) No		
Other notices No		
End of section		



Ownership - WA450724

Tenure of the property

Freehold

Title number

WA450724

Whole freehold being sold

Yes



Ownership - CYM653401

Tenure of the property

Freehold

Title number

CYM653401

Whole freehold being sold

Yes



Ownership - WA481742

Tenure of the property

Freehold

Title number

WA481742

Whole freehold being sold

Yes



Parking

Type of parking available

Garage, Driveway, Off Street, Rear, Private

Controlled parking in place

No

Disabled parking available

Not known

Electrical vehicle charging point at the property

No



Shared contributions No	
Neighbouring land rights No	
Attempts to restrict access No	
Public right of way No	
Rights of light No	
Rights of support No	
Rights created through custom No	
Rights to take from land No	
Mines and minerals under the property No	

Church chancel	liability
----------------	-----------

No

Other rights

No



Services crossing the property

Pipes, wires, cables, drains from propertyNot known

Pipes, wires, cables, drains coming to property

Not known

Formal or informal agreements for services crossing the property

Not known



Specialist issues

Subsidence or structural faults No	
Property treated for dry rot, wet rot or damp No	
Ongoing health or safety issues at the property No	
Japanese knotweed at the property or neighbouring land Not known	
Asbestos at the property No	
End of section	



End of section

Type of construction

Property is built with standard forms of construction Yes
Spray foam installed at the property No
Details of any accessibility adaptations at the property No accessibility adaptations
→ Building safety
Building safety issues at the property No
↓ Loft
Property has access to a loft
Yes
How the loft is accessed
From bedroom
Loft boarded No
Loft insulated Yes



Water & drainage

√ Water

Mains water connected to the property Yes

Mains water supplier

Welsh water

Location of the stopcock

Utility room

Mains water supply metered

No

↓ Drainage

Surface water drainage connected to the property

Yes

Mains foul drainage connected to the property

Yes

Mains foul drainage supplier

Welsh water

Maintenance agreements in place for the drainage system

Nο